



Pos.	Part Number	Description {Qty.}	F/C	Pos.	Part Number	Description {Qty.}	F/C
1	352546	Drive Coupling	40	13	347948	Screw {4}	89
2	354744	Bit Retainer Spring	27	14	902316	Motor Housing Assy.	71
3	352510	Bushing	51	15	902304	Battery Pack 3.6V	18
4	352545	Collet 1/4" Hex	91	16	903976	Battery Charger 120V	18
5	352532	Pin {2}	66	17	354463	Motor Flange	3
6	352511	Lock Ring	67	18	356036	Eccentric Gear {3}	34
7	357464	Ring Gear Assembly	32	19	357447	Bit Cover	70
8	356033	Eccentric	53	20	357448	Spring	27
9	356652	Gear {3}	31	21	350012	Screw	89
10	354457	Pinion Gear	33	+ 22	904488	Label	9
11	352716	Motor 3.6V	19	+ 23	2 610 911 689	Nameplate	9
12	357411	Switch On/Off REV.	16				

+ = Not Illustrated * = As Required F/C = Failure Code AW = Refer to AW Labor Time Chart